Oil Field Environmental Incident Summary

Responsible Party: RIM OPERATING, INC. **Well Operator:** RIM OPERATING, INC.

Well Name: HMU 9-34XHR

Field Name: HOFFLUND Well File #: 7594

Date Incident:10/20/2016Time Incident:17:45Facility ID Number:County:WILLIAMSTwp:154Rng:95Sec:9Qtr:

Location Description:

Submitted By: Troy Johnson Received By:

Contact Person: Jason Rouse

5 INVERNESS DRIVE EAST ENGLEWOOD, CO 80112

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

	Spilled	Units	Recovered	Units	
Oil	4	Barrels	4	Barrels	
Brine	1	Barrels	1	Barrels	

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:Not Applicable

Areal Extent:

Followup Units

Potential Environmental Impacts:

Not Applicable

Action Taken or Planned:

We had a crew nearby cleaning out a production tank at the time of the incident. That crew and equipment was diverted to this site and began cleaning up the spilled fluids immediately. The crew worked into the night and had 90% of the fluid and contaminated soil cleaned up before before they left. The same crew was back at the site first today to finish the cleanup.

Wastes Disposal Location: Prairie Disposal or IHD Disposal

Agencies Involved: NDIC - Field Inspector Marc Binns

Updates

Date: 10/21/2016 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, was contained within diking according to the report. NDIC retains oversight.